

Exhibit 63

**Tripp's August 2018 tweets (Tesla
TES-TRIPP_0000919, TES-
TRIPP_0000936, TES-
TRIPP_0000949, and TES-
TRIPP_0000952)**




Martin Tripp

@trippedover

Follow



Are any of these VIN's YOUR car? If so, you have a module(s) that IS punctured/dented/damaged. [#TSLA](#) [#TSLAQ](#) [@elonmusk](#) (Subsidy Fraud-Boy)



2:09 PM - 15 Aug 2018

58 Retweets 140 Likes





Martin Tripp

@trippedover

Follow



Here's what this [REDACTED] looks like [#TSLA](#) [#TSLAQ](#)



2:13 PM - 15 Aug 2018

8 Retweets 34 Likes




**Martin Tripp**

@trippedover

[Follow](#)

Now let's look at Bandolier scrap from 1/1/18 (although 1/1 to 3/21 is actually missing most likely due to accounting fraud (hard to prove though) [#TSLA](#) [#TSLAQ](#) Keep in mind, the \$ values are from MOS. Does NOT include overhead cost, etc.



2:19 PM - 15 Aug 2018

11 Retweets **33** Likes




Martin Tripp

@trippedover

Follow

>

What's that? You want to see Module scrap?
Here ya go! [#TSLA](#) [#TSLAQ](#)



2:21 PM - 15 Aug 2018

3 Retweets 28 Likes

